

CONVERSION TABLE

Fractions		Decimal	mm
	1/64	.0156	.3969
	1/32	.0313	.7938
	3/64	.0469	1.1906
1/16		.0625	1.5875
	5/64	.0781	1.9844
	3/32	.0938	2.3813
	7/64	.1094	2.7781
1/8		.1250	3.1750
	9/64	.1406	3.5719
	5/32	.1563	3.9688
	11/64	.1719	4.3656
3/16		.1875	4.7625
	13/64	.2031	5.1594
	7/32	.2188	5.5563
	15/64	.2344	5.9531
1/4		.2500	6.3500
	17/64	.2656	6.7469
	9/32	.2813	7.1438
	19/64	.2969	7.5406
5/16		.3125	7.9375
	21/64	.3281	8.3344
	11/32	.3438	8.7313
	23/64	.3594	9.1281
3/8		.3750	9.5250
	25/64	.3906	9.9219
	13/32	.4063	10.3188
	27/64	.4219	10.7156
7/16		.4375	11.1125
	29/64	.4531	11.5094
	15/32	.4688	11.9063
	31/64	.4844	12.3031
1/2		.5000	12.7000

Fractions		Decimal	mm
	33/64	.5156	13.0969
	17/32	.5313	13.4938
	35/64	.5469	13.8906
9/16		.5625	14.2875
	37/64	.5781	14.6844
	19/32	.5938	15.0813
	39/64	.6094	15.4781
5/8		.6250	15.8750
	41/64	.6406	16.2719
	21/32	.6563	16.6688
	43/64	.6719	17.0656
11/16		.6875	17.4625
	45/64	.7031	17.8594
	23/32	.7188	18.2563
	47/64	.7344	18.6531
3/4		.7500	19.0500
	49/64	.7656	19.4469
	25/32	.7813	19.8438
	51/64	.7969	20.2406
13/16		.8125	20.6375
	53/64	.8281	21.0344
	27/32	.8438	21.4313
	55/64	.8594	21.8281
7/8		.8750	22.2250
	57/64	.8906	22.6219
	29/32	.9063	23.0188
	59/64	.9219	23.4156
15/16		.9375	23.8125
	61/64	.9531	24.2094
	31/32	.9688	24.6063
	63/64	.9844	25.0031
1		1.0000	25.4000